



Cracow University of Technology
Faculty of Mechanical Engineering
DEPARTMENT OF
TECHNOLOGY
MACHINES AND TOOLS



Definition of milling operations in the Esprit CAM software

You will learn:


- About SolidMill Traditional machining technology and machining cycles
 - How to create a milling tool
 - How to create features for milling operations
 - How to create a stock model
 - Techniques to quickly remove stock material
- Drilling techniques for hole patterns and a milled hole
 - Simulation of machining process

1. The ESPRIT Graphical User Interface (GUI)

Let's start by taking a look at the ESPRIT screen. This window is displayed when you create a new file or open an existing one.

The ESPRIT window contains:


1. Menus and default toolbars along the top of the screen. You can select commands from the menus or from toolbars.
2. A graphic work area where you can view your work. This is the largest area of the screen.
3. The Prompt area, at the bottom left of the screen, displays prompts that tell you what to do next. Always pay attention to what the prompt is telling you.
4. The Status area, at the bottom of the ESPRIT screen, provides dynamic information about the current work environment. As you select commands or move the cursor, the information is constantly updated.



ESPRIT also provides two specialized windows that provide additional information about the parts you are working on and provide an excellent way to manage your work.

5. The Project Manager consists of a tabbed set of windows that list every feature, every cutting tool, and every operation in the current session. The Project Manager lets you manage, sort, and reorder these items. To view the Project Manager, press the F2 key or click Project Manager on the View menu.


6. The Property Browser displays the specific properties of any item selected in the graphic work area or the Project Manager. The types of properties displayed depend on the type of item selected. You can view and change individual properties for the selected item. To view the Property Browser, click Properties on the View menu or hold down the Alt key as you press Enter.



Default Toolbars

The default toolbars are located near the top of the ESPRIT screen.

1. The Standard toolbar has file management commands that let you create, open, save, and print files. This is also where you can find the Copy command when you want to copy elements in the work area.
2. The View toolbar has several commands that let you control the display in the work area, such as zooming and rotating the view plus commands that let you choose whether to display parts in shaded or wire frame modes.
3. The Edit toolbar gives you selection tools that let you filter the types of elements that can be selected or automatically select (group) multiple elements from the selection of a single element.
4. The Layers and Planes toolbar has commands for creating and selecting work planes, layers, and view planes.



The Smart Toolbar

Use the Smart toolbar to quickly display and hide ESPRIT toolbars based on the type of work you want to do.

The first three icons on the toolbar relate to the machining modes in ESPRIT: milling, turning, and wire EDM.



If you click “Switch to SolidMill”, the toolbar is updated to display commands that let you create milling tools and operations. If you click “Switch to SolidTurn”, the milling commands are hidden and new commands display that let you create turning and mill/turn operations and tools.




Displaying the XYZ Axis and the UVW Axis

You can display two types of axes in the work area:

XYZ Axis: The global axis positioned at the global origin point

UVW Axis: The local axis of the current work plane

The display of the two axes is controlled on the View menu.



Shaded and Wireframe Displays

For solids and surfaces, you can set the display to shaded or wireframe mode.



Shaded Wire: Creates a shaded image with wireframe.

Shaded: Creates a shaded image.

Hidden Wireframe.

Wireframe.

Views

ESPRIT provides several standard view orientations.





When you change from one view plane to another, the display in the work area rotates to the new view orientation and the display automatically zooms to fit all elements within the screen.


2. SolidMill Traditional Machining Cycles


All SolidMill Traditional machining cycles are displayed on the SolidMill Traditional toolbar and on the Machining menu under SolidMill Traditional. To display the SolidMill Traditional toolbar, click 'Switch to SolidMill' on the Smart toolbar and then click SolidMill Traditional.





 Facing - Removes a flat portion of stock material based on a feature that matches the stock perimeter. SolidMill Facing quickly removes material at the depth (or depths) you specify with simple linear passes followed by a final contouring pass around any islands to provide a uniform amount of stock on wall areas. The linear and contouring passes are combined into a single operation to save you time and to guarantee a consistent amount of stock on floors and walls.


 Pocketing - Removes material inside a closed boundary. Within a single pocketing operation, you have the option to create separately definable phases for roughing, wall finishing, and floor finishing passes that each let you use a different tool. When a pocket or face profile feature is chosen, the operation automatically finds any subordinate islands within the feature boundary.


 Trochoidal Pocketing - Removes material inside a closed boundary using the fastest possible feed rates. Trochoidal Pocketing quickly roughs parts at a constant material removal rate and provides multiple levels of control over tool motion pattern, feed rates, and cutter load. Although developed for high-speed machining, Trochoidal Pocketing brings benefits to any type of machine by providing a more constant tool load and a better surface finish.


 Contouring - Creates vertical or tapered cuts along the contour of a selected profile. Within a single contouring operation, you have the option to create separately definable phases for roughing and finishing. The same tool is used for both roughing and finishing, although you can define different incremental depths for finishing passes as well as different speeds and feeds.


 Rest Machining - Creates an operation to remove material remaining from previous operations. A rest machining operation can be applied to any existing SolidMill Traditional operation. The previous operation becomes the “parent” operation and the rest machining operation applied to it becomes the “child” operation. The child operation inherits many of the settings from the parent operation. The parent operation is used as the basis for calculating the areas to machine.

 Drilling - Creates a drilling operation. Several types of drilling cycles are supported, including canned cycles.

 Spiraling - Creates either spiral or helical cutting passes based on the selection of a feature with a circular shape or a PTOP feature.

 Threading - Creates a standard threading or single-point threading operation using basic milling technology.

 Manual Milling - Creates rapid or feed moves based on manually selected elements or coordinate locations. Manual Milling creates a tool path on the centerline of the tool without compensation.

 Wire Frame Milling - Creates a milling operation based on wire frame geometry. This command lets you create a simple freeform milling operation from planar geometry. Two separate profiles are used. One profile is swept along the other to create a 3-dimensional shape for the toolpath.

3. Open the part file

On the Standard toolbar, click Open.




Browse and select the following file: milled_part.esp.

Set the view to 'Isometric'.



If the Project Manager is not displayed, press F2.



4. Create a milling tool

This file already contains several types of tools, such as end mills, drills, and even a custom mill for cutting the milled hole.

You will learn how to create a face mill that will be used to remove the stock at the top of the part.

Milling tools can be created from the Tool Manager or from commands on the Milling Tools toolbar.




ESPRIT provides an extensive list of pre-defined milling tools. If you use a very specific type of tool that is not on the list, you can create a Custom Mill from geometry you define.

Instructions on how to create a custom mill are provided in ESPRIT Help.

The Tool Manager

All cutting tools are managed on the Tools tab of the Project Manager. The Tool Manager lets you create, edit, copy, rename, and delete tools. You can also transfer tools between the Tool Manager and the KnowledgeBase.

The Tool Manager displays all the available tools in the current document. Tools are grouped by where they are mounted on the machine: on a milling head or a lathe turret (for a mill-turn machine).



Create a face mill tool

You will create a new face mill tool with a diameter of 60 mm. This face mill has 6 cutting inserts that have a rectangular shape.

On the Smart toolbar, click Milling Tools.




Click Face Mill.




On the General tab:

- Set 'Tool ID' to 'FM 60'
- Set 'Tool Number' to 1



On the Machine tab:

- Set 'Movement X, Y, Z' to 'Home' for all three positions
- Set 'Turret Name' to 'Head'




The Machine tab configuration panel includes a vertical toolbar on the left with icons for a tool change, a wrench, a blue turret, a silver tool holder, and a yellow shank. The main panel is titled 'Tool Change' and contains the following settings:

- Movement X,Y,Z:** Three dropdown menus, all set to 'Home'.
- Position X,Y,Z:** Three input fields with values 0.000000, 0.000000, and 125.000000.
- Mounting:**
 - Turret Name:** Dropdown menu set to 'Head'.
 - Station Name:** Dropdown menu set to 'Station:1'.
 - Axis Orientation:** Dropdown menu set to 'X+'.
- Vector X,Y,Z:** Three input fields with values 1.000000, 0.000000, and 0.000000.
- Tool Shift X,Y,Z:** Three input fields, all with values 0.000000.

On the Holder tab:

- Set 'Holder Diameter' to 60
- Set 'Overall Length' to 100
- Set 'Tool Length' to 80




The Holder tab configuration panel includes the same vertical toolbar as the Machine tab. The main panel is titled 'Holder' and contains the following settings:

- Holder Diameter:** Input field with value 60.000000.
- Overall Length:** Input field with value 100.000000.
- Tool Length:** Input field with value 80.000000.

On the Shank tab:

- Set 'Type' to 'Cylindrical'
- Set 'Shank Diameter' to 30
- Set 'Cutting Length' to 1.5




The Shank tab configuration panel includes the same vertical toolbar as the Machine tab. The main panel is titled 'Shank' and contains the following settings:

- Type:** Dropdown menu set to 'Cylindrical'.
- Shank Diameter:** Input field with value 30.000000.
- Tool Length:** Input field with value 80.000000.
- Cutting Length:** Input field with value 1.500000.
- Top Diameter:** Input field with value 30.000000.
- Bottom Length:** Input field with value 40.000000.
- Shank Angle:** Input field with value 45.000000.
- Import Geometry:** Button labeled 'Browse...'.

On the Cutter tab:

- Set 'Tool Diameter' to 60
- Set 'Bottom Clearance' to 10
- Set 'Number of Inserts' to 6
- Set 'Insert Type' to 'Rectangular'
- Set 'Corner Radius' to 1
- Set 'Insert Width' to 30
- Set 'Insert Height' to 10.


Click OK to add the new tool to the Tool Manager.



The image shows two configuration panels for a tool. The top panel is titled 'Cutter' and contains the following fields: Tool Diameter (60.000000), Bottom Clearance (10.000000), Orientation Angle (0.000000), Cutting Length (1.500000), Number Of Inserts (6), Shank Diameter (30.000000), and Tool Length (80.000000). The bottom panel is titled 'Insert' and contains the following fields: Insert Type (Rectangular), Corner Radius (1.000000), IC Diameter (10.000000), Insert Width (30.000000), Insert Height (10.000000), and Diamond Angle (1.000000). To the left of the panels are icons for different tool types: a mill bit, a drill bit, a reamer, and a tap.

Cutter	
Tool Diameter	60.000000
Bottom Clearance	10.000000
Orientation Angle	0.000000
Cutting Length	1.500000
Number Of Inserts	6
Shank Diameter	30.000000
Tool Length	80.000000

Insert	
Insert Type	Rectangular
Corner Radius	1.000000
IC Diameter	10.000000
Insert Width	30.000000
Insert Height	10.000000
Diamond Angle	1.000000



The image shows a 'Project Manager' window with a tree view on the left and a table of items on the right. The tree view shows a folder named 'Head (17 items)'. The table has columns for 'Id', 'No.', and 'Dia./Rad.'. The 'Id' column contains icons for different tool types. The 'No.' column contains numbers. The 'Dia./Rad.' column contains values. The table is sorted by 'No.' in ascending order. The 'FM 60' tool is highlighted in blue.

Id	No.	Dia./Rad.
Station:1 Ball End Mill...	2	10
Station:1 Bull Nose D1...	3	16
Station:1 CustomSlot	17	28
Station:1 DR 06.6	27	6.6
Station:1 DR 11	39	11
Station:1 DR 30	11	30
Station:1 EM 10	7	10
Station:1 EM 10.0	66	10
Station:1 EM 20 Fi	4	20
Station:1 EM 20 Rough	5	20
Station:1 EM 3.0 Fi	10	3
Station:1 EM 30 Rough	12	30
Station:1 EM 5.0 Rough	9	5
Station:1 EM15	8	15
Station:1 EMF 8.0	6	8
Station:1 FM 60	1	60
Station:1 SD 25	79	25

5. Create milling features


Milling features have machining properties that help to automate milling operations. These properties include depth, draft, cutting side, and whether material is removed on the inside or outside of the feature. These properties assist the user because SolidMill technology is designed to use these properties each time a milling operation is created. If the feature is modified to change any of the machining properties, such as a change in the depth property, any milling technology that is applied to that feature can be updated quickly by simply rebuilding the operation.

When features are created on a solid model, ESPRIT uses automatic feature recognition to analyze the part geometry and automatically create the appropriate features for milling operations. The user is not limited to selecting only the solid model. The user can also select sub-elements of a solid model, such as faces and face loops, to create features on a specific portion of the solid model.

Set the work plane

When automatic feature recognition is used, the direction of the W axis of the active work plane controls the direction of feature recognition. This allows you to create features automatically on different sides of a part.

Make sure the work plane is set to 'XYZ'.



Recognize the pockets

In the status area, make sure HI mode and SUB-ELEMENTS mode are active.



On the Smart toolbar, click Create Features.





Pocket Feature Recognition uses the 'Maximum Diameter' parameter located in the Feature Parameters dialog to recognize cylindrical pockets. Any cylinder with a diameter greater than the 'Maximum Diameter' will be recognized as a pocket.


Click Feature Parameters.



- Click the arrow button next to 'Max Diameter' and use HI mode to select the edge of a hole on the corner of the part
- Click OK



- Select the solid model
- Click Pocket 




Rename the pocket features







Features for the pockets and island were created automatically and placed in a folder in the Feature Manager.

It is helpful to give descriptive names to features. This makes it easier to select the correct feature when you want to apply a machining operation and it is extremely helpful to other users if they need to modify operations at a later time.


- Click the Features tab in the Project Manager
- Expand the folder for the pocket
- Right-click on the feature for the pocket in the middle of the part
- Select 'Rename'
- Rename the feature to 'Medium Pocket' and press Enter





- In the same way, select the feature for the slot and rename it 'Slot'
- Rename the small pocket 'Small Pocket'
- Rename the cylindrical pocket 'Milled Hole - Upper'







Recognize the boundary

- Click Face Profiles 
- Use HI mode to select the face loop around the top of the part
- Click OK




Recognize the drilled holes




- Click Holes 
- The value for 'Max Diameter' is already set to the diameter of the hole you selected for the pocket features
- Click OK
- Rename the group of large holes 'Counterbore'
- Rename the group of small holes 'Countersink'



Create a hole feature for the milled hole

It is more efficient to pre-drill the milled hole before applying a milling operation. To do this, you can create a simple Hole feature that matches the size of your largest drill.

- Click Holes 
- Set 'Max Diameter' and 'Min Diameter' to 42
- Click OK
- Press Alt+Enter to display the Property Browser
- In the Feature Manager, select the new hole feature
- In the Property Browser, change the value for the Depth property to 38.1
- Change the value for the Diameter property to 30 and press Enter
- Close the Property Browser



6. Create a stock model

Stock models for milling operations are created in Simulation Parameters on the Simulation toolbar.

Stock models are created as solid models that aid in the visualization of material removal during the simulation process. Stock models can be defined in a variety of ways: from an existing solid model, from a feature, from an external file, and from points that define a block.

In this lesson, you will create the stock model from a chain feature that defines the shape of the boundary.


On the Smart toolbar, click Simulation.





Click Simulation Parameters.







- Click the Solids tab
- Set 'Type' to 'Stock' and set 'Create From' to 'Extrusion'



- Click the arrow button and select the feature 'Stock Profile' in the work area
- Set 'Z+' to 1
- Set 'Z-' to 53.1



- Set 'Indexing' to 'None'
- Click Add
- Click OK
- To view the new stock model, click Single Step 
- Click Stop to exit simulation mode 



7. Remove excess material

In this project, the part is cut from standard rectangular stock. The first thing you need to do is remove the excess material from the top and around the sides of the part.

To do this, you will first create a facing operation to quickly remove as much stock as possible from the top of the part. Then you will create a 3D contour around the island on the top face. You will finish by roughing and finishing the outer profile of the part.

Face the top of the part

For this facing operation, there is an island on the face that must be avoided. The Facing command lets you select and avoid islands and pocketed areas.

This operation will start slightly below the selected feature and cut at incremental depths of 8mm in a simple back and forth tool motion. A stock allowance of 0.5 mm will remain on the walls of the island after the operation is complete. No stock allowance will remain on the floors.

✎ As you enter values on the technology page you can use the Tab key to move from one parameter to the next. Be careful not to press the Enter key. Pressing the Enter key will apply the current settings to the selected feature.

In the Feature Manager, select the feature 'Stock Profile'.


On the Smart toolbar, click SolidMill Traditional.



Click Facing.



- On the dropdown menu, click 'System Default All' to reset all the technology parameters to the system default settings



- Under 'Operation Name', type Facing
- Select the tool 'FM 60' for 'Tool ID'

Project Manager

OK Cancel Help

General

Operation Name

Facing

Strategy

Tool Selection

Tool ID

FM 60

Links

Feeds and Speeds

Cut Speed RPM, SPM	0	0	⚠
XY Feedrate PM, PT	0.000000	0.000000	⚠
Z Feedrate PM, PT	0.000000	0.000000	⚠
Const. Removal Rate	No		
Use Feed and Speed KB	No		

Comment

Features Tools Operations SolidMill - Facing

- Click the Strategy tab
- Set 'Overhang Direction' to 'One Way'
- For detailed information about this setting, click Help.
- Set 'Include Islands' to 'Yes'
- Set 'Stock Allowance Walls' to 0.5
- Set 'Total Depth' to 15
- Set 'Incremental Depth' to 8
- Set 'Starting Depth' to -1

Project Manager

OK Cancel Help

General

Strategy

Cutting Strategy

Strategy

Zigzag

One Pass

No

Optimal Cutting Angle

Yes

Bridge Movement

Segments

Step Over, % of Diameter

30.000000 50.000000

Overhang, % of Tool

30.000000 50.000000

Overhang Direction

One Way

Include Islands

No

Links

Stock Allowance

Stock Allowance Walls

0.500000

Stock Allowance Floors

0.000000

Depths

Total Depth

15.000000

Incremental Depth

8.000000

Starting Depth

-1.000000

Retract for IDepth


Partial Depth

Incr. Depth Calculation


Varying

Features Tools Operations SolidMill - Facing

- Click the Islands tab
- Click inside 'Island Features' and then select the island feature in the work area






- Click the Links tab
- Set 'Entry Mode' to 'Rapid Down, Feed Over'
- Set 'Exit Mode' to 'Feed Over, Rapid Up'
- Click OK




Create a simple 3D milling operation

For this operation, you will use two existing features. The 'Wireframe Drive Curve' defines the curved profile for the walls around the island on the face. The 'Wireframe Basic Curve' feature is located on the top face of the island and defines the path the profile will follow.

- Select the feature 'Wireframe Basic Curve'
- Click Wire Frame Milling 
- On the drop-down menu, click Open
- Open the following technology file: Processes\M1-Wire_Frame_Milling.prc
- Click the Wire Frame tab
- Click the arrow button next to 'Drive Curve' and select the drive curve feature in the work area







- Notice that 'Machine Along' is set to 'Basic' so that the flow lines of the tool path will follow the shape of the basic curve
- Click OK




Rough and finish the outer profile

To cut the external profile of the part, you will first rough the profile with a 30mm end mill that will leave 0.5 mm stock on the walls and then finish with a 20mm end mill. Because the roughing and finishing operations use very different settings, you will create two separate Contouring operations.

- Select the profile feature on the boundary of the part
- Click Contouring 
- Open the file: M2-Contour_Rough.prc
- Click the Strategy tab
- Notice that there will be 1 rough pass and no finish pass. 'Stock Allowance Walls' is set to 0.5 and 'Incremental Depth' is set the same as the diameter of the tool.
- Click OK



- With the same feature selected, click Contouring 
- Open the file: M3-Contour_Finish.prc
- On the Strategy tab, 1 rough pass is generated with no stock allowance
- Click OK

OK Cancel Help

General



Cutting Strategy

# of Rough Passes	1
Finish Pass	No
Cutting Strategy	Climb
Process Order	Width
Spiral Move	No

Stock Allowance


Stock Allowance Walls	0.000000
Stock Allowance Floors	0.000000

Depths

Total Depth	38.100000	
Incremental Depth	20.000000	
Starting Depth	0.000000	
Retract for IDepth	Surface Clearance	
Tapered Wall Angle	0.000000	

Compensations

Features Tools Operations SolidMill - Contouring





8. Cut the pockets and slot

The part in this project contains two pockets and a slot. ESPRIT offers two types of pocketing operations that you will use to cut each pocket: Trochoidal and Traditional.


Rough the medium pocket

To mill the medium pocket, you will first remove as much material as possible as quickly as possible with a Trochoidal Pocketing operation. A stock allowance of 0.5mm will remain on the walls and floors of the pocket.

- Inside the 'Pocket' feature group, select the feature 'Medium Pocket'
- Click Trochoidal Pocketing 
- Open the file: M4-Rough_Pocket.prc
- On the Strategy tab, notice that 'Trochoid' tool motion is used and that the trochoid step over is set to 25% of the tool diameter when ESPRIT detects that the tool is fully engaged in the material.
- For details on trochoidal tool motion, click the Help button
- Click OK





Notice that the tool path starts in the largest area of the pocket and spirals outward until it reaches an obstacle. Then the tool path changes to adjustable curves that adapt to the shape of the pocket.



Finish the medium pocket

You will use a traditional Pocketing operation to first finish the walls and then the floors of the pocket.

- Select the feature 'Medium Pocket'
- Click Pocketing 
- Open the file: M5-Finish_Pocket.prc
- On the Strategy tab, notice that 'Rough Pass' is set to 'No' and both 'Wall Finish Pass' and 'Floor Finish Pass' are set to 'Yes'





- Click the Wall Finish tab
- A single contouring pass will be applied to the walls with a stock allowance of 0.2 mm

The screenshot shows the 'SolidMill - Pocketing' dialog box with the 'Wall Finish' tab selected. The 'General' section shows 'Tool ID' as 'EM 10'. The 'Strategy' section shows '# of Passes' as '1', 'Cutting Strategy' as 'Climb', 'Passes Exist At' as 'Each Z Level', and 'Passes Around' as 'Islands & Boundary'. The 'Stock Allowance' section shows 'Stock Allowance Walls' as '0.200000' and 'Stock Allowance Floors' as '0.000000'. The 'Compensations' and 'Lead-In/Out' sections are also visible.

- Click the Floor Finish tab
- The floor of the pocket will be finished with a constant step over of 2.5 mm and no stock allowance


The screenshot shows the 'SolidMill - Pocketing' dialog box with the 'Floor Finish' tab selected. The 'General' section shows 'Tool ID' as 'EM 10'. The 'Strategy' section shows 'Cutting Strategy' as 'Climb', 'Passes Exist At' as 'Both', 'Incremental Depth' as '0.000000', and 'Step Over, % of Diameter' as '2.500000' (25%). The 'Stock Allowance' section shows 'Stock Allowance Walls' as '0.000000' and 'Stock Allowance Floors' as '0.000000'. The 'Entry/Exit' section is also visible.



- Click the Links tab
- 'Passes Order' is set to 'R | AW | AF'. This means that any roughing passes will be applied first. 'AW' means that All Walls will be cut next. 'AF' means that All Floors will be cut last.
- Click OK



Remove material in the corners


To remove any material remaining in the corners, you will apply a Rest Machining operation.


- Select the feature 'Medium Pocket'
- Click Rest Machining 
- Open the file: M6-Corner_Finish.prc
- On the Strategy tab, notice that the tool motion for area clearing is set to 'Concentric In'. Area clearing is applied when an area has more than one exposed edge of material (for example, between a wall and an island). Corner clearing is applied when there is only one exposed edge (corners).
- Click OK



Rough and finish the small pocket


You will use a single pocketing operation to rough the pocket and then finish the walls using a different tool.



- Select the feature 'Small Pocket'
- Click Pocketing 
- Open the file: M7-Small_Pocket.prc
- Click OK



Cut the slot

To cut the slot, you will use a traditional Pocketing operation using a tool with a diameter the same width as the slot. The tool will enter the material using a ramping move and then cut the slot with a single pass.

- Select the feature 'Slot'
- Click Pocketing 
- Open the file: M8-Slot.prc
- Click the Rough tab and notice that 'Entry Mode' is set to 'Ramp Along Pass'. The tool will enter the slot with a long ramping pass at a 10 degree angle.
- Click OK





9. Mill and drill the holes


This part has different types of holes, including a milled hole. For this project, you will create drilling and spiraling operations depending on the type and size of the hole.



Pre-drill and mill the large hole

The milled hole has a diameter of 42 mm. You will cut this hole in two steps. First, you will drill the hole with a 30mm drill. Then, you will create a Spiraling operation to mill the upper diameter to a depth of 30mm.

- Select the Hole feature for the milled hole
- Click Drilling 
- Open the file: M9-Drill_Milled_Hole.prc
- Click OK






- In the 'Pocket' feature group, select the feature 'Milled Hole - Upper'
- Click Spiraling 
- Open the file: M10-Spiral.prc
- On the Strategy tab, notice that 'Strategy' is set to 'Tangent Arcs'. The tool path will be created as arcs that are tangent to one another.
- Click OK





Drill the holes

- In the Feature Manager, right-click on the feature 'Counterbore' and select File > Open Process
- Open the file: M11-Counterbore.prc
- Again, right-click on the feature 'Counterbore' and open the file: M12-Drill_Counterbore.prc



- Right-click on the feature 'Countersink'
- Open the file: M13-Countersink.prc
- Again, right-click on the feature 'Countersink' and open the file: M14-Drill_Countersink.prc
- To view the settings for any of these operations, double-click on an operation to open the technology page







10. Simulate milling operations

Operations are simulated in the same order as they are listed in the Operation Manager.

On the Smart toolbar, click Simulation.



- Click 'Run' to start the simulation .
- Click 'Pause' to temporarily stop the simulation .
- Click 'Run' again to restart the simulation .
- When the simulation is finished, click 'Stop' .

